## IN THE UNITED STATES PATENT & TRADEMARK OFFICE

ATTORNEY DOCKET NUMBER: 200208474-1

IN RE APPLICATION OF: U.S. Patent No. 7,800,253

USPTO CONFIRMATION CODE: 7631

APPLICATION NO.: 10/743,230

FILED: Dec. 21, 2003

EXAMINER: ROBERT L DEBERADINIS

charge the amount to the same Deposit Account.

**GROUP ART UNIT: 2836** 

FOR: TRANSMITTING SIGNALS OVER INTERCONNECT CARRYING DIRECT CURRENT FROM POWER SUPPLY TO ELECTRONIC DEVICE

## 37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION

## HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS

Sir:

The following is a request for a certificate of correction in Serial Number 10/743,230, now Patent Number 7,800,253.

A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent.

166 12 16	equired, please charge the amount to Deposit Account No. 082025.
	All errors were the fault of the applicant and, accordingly, please charge \$100.00 Deposit Account No. 082025. In the event that a further fee is required, please

All errors were the fault of the USPTO, no fee required. In the event that a further

The errors were the fault of both the applicant and USPTO and, accordingly, please charge \$100.00 to our Deposit Account No. 0.82025. In the event that a further fee is required, please charge the amount to the same Deposit Account.

The exact location where the error appears in the patent and patent application is as follows:

In column 9, line 46, in Claim 21, delete "components" and insert - - components, - -, therefor.

(Amendments to claims filed on Mar. 8, 2010, page 7, in claim 24, line 3)

The requested correction is attached on Form PTO 1050.

Respectfully Submitted

26 February 2011 /Steven R. Ormiston/
DATE Name: Seven R. Ormiston

Registration No.: 35974

Attorney/Agent of Record

HEWLETT-PACKARD COMPANY Intellectual Property Administration 3404 E. Harmony Road Mail Stop 35 Fort Collins, CO 80528 G. S. Pinerst and Trademark Office; U.S. DEPARTMENT OF COMMERCE Under the Paperwork Reduction Act of 1995, no presons are required to respond to a reliferition of information unless it displays a vasid OAB control number. (Also Ferm PTP-1659)

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO. : 7.800,253

APPLICATION NO.: 10/743,230

ISSUE DATE : Sep. 21, 2010

INVENTOR(S) : Nikholas Hubbard et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 9, line 46, in Claim 21, delete "components" and insert - - components, - -, therefor.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Hewlett-Packard Company Intellectual Property Administration 3404 E. Harmony Road

Mail Stop 35

Fort Collins, CO 80528

This collision of information is required by 3 CPR 1.322 and 3.232, and 1.324. The information is required to obtain or retinit a breaffer the the guide of the time (LFPO) to approximate an application. Geologicalitation is generated by \$1.52.51.22 and \$3.75.81.31. This collection is estimated to take 1.0 live the complete, multidag guidelings, preparing, and submitting the completed application from to the USPTO. Time will vasir deposing upon the individual case. Any comments on the amount of one you require to complete this form and/or unagestation for reducing this hand, build be sent to the Cite Information Gibber. US better and of Technism Colline. 20. Technism Colline